

***Dedicated to the people who lost their lives and injured
by the 2023 Pazarcık and Ekinözü Earthquakes of Türkiye***

**A QUICK REPORT
ON
PAZARCIK AND EKİNÖZÜ EARTHQUAKES
(TÜRKİYE) OF FEBRUARY 6, 2023**

Ömer AYDAN* and Reşat ULUSAY**

** University of the Ryukyus, Okinawa, Japan*

*** Hacettepe University, Ankara, Türkiye*

15 February 2023

A QUICK REPORT ON PAZARCIK AND EKİNÖZÜ EARTHQUAKES (TÜRKİYE) OF FEBRUARY 6, 2023

Ömer AYDAN* and Reşat ULUSAY**

** University of the Ryukyus, Okinawa, Japan*

*** Hacettepe University, Ankara, Türkiye*

ATTENTION

Please note that this document is prepared with a sole purpose to provide an overview of various aspects of the earthquake for researchers, who would be involved with this earthquake.

The pictures and some figures are obtained from various sources with due references available in various web-sites. The figures drawn by the authors of this report are cited as (DbA) next to them.

The major source of the pictures relevant to the aspects of this document are obtained from the web-sites of the mass media of Türkiye and relevant institutes and they are gratefully acknowledged for the information through images and data of the earthquake:

<https://www.aa.com.tr/tr>

<https://www.dha.com.tr/>

<https://www.trt.net.tr/>

<https://www.emsc-csem.org/#2>

<https://www.usgs.gov/>

<https://www.mta.gov.tr>

<https://www.koeri.boun.edu.tr>

<https://www.afad.gov.tr>

<https://www.maxar.com/open-data/turkey-earthquake-2023>

CONTENT

LOCATIONS

MAIN CHARACTERISTICS OF THE EARTHQUAKES

TECTONICS

GEOLOGY

PRE- AND POST- SEISMICITY

FOCAL MECHANISMS AND ASSOCIATED STRESS FIELD

SURFACE DEFORMATION FROM GPS and DINSAR

STRONG MOTION RECORDS

TRANSPORTATION FACILITIES

- Roadways

- Tunnels

- Railways

- Ports

GEOTECHNICAL DAMAGES

- Soil Slopes

- Rock Slopes

- Rock Falls

- Ground liquefaction and lateral spreading

DAMS

LIFELINES

DAMAGED AND COLLAPSED STRUCTURES

- RC Buildings

- Masonry Structures

- Historical Structures

SEARCH AND RESCUE

EVACUATION AND IMMEDIATE HOUSING

UNUSUAL OBSERVATIONS

References



LOCATIONS

PAZARCIK EARTHQUAKE

EMSC manual location

M:7.8 2023/02/06 - 01:17:36 UTC
Lat: 37.17 Lon: 37.08 Depth: 20 km

Population: 59 Millions inhabitants in a radius of 400 km from the earthquake epicenter



Depth

- ★ 0 - 40 km
- ★ 40 - 80 km
- ★ 80 - 150 km
- ★ 150 - 300 km
- ★ > 300 km

- 20 km
- Political boundaries
- Tectonic plates boundaries (Bird, P. [2003])

Last updated: 2023-02-06 at 08:21 UTC

(from CSEM-EMSC)



EKİNOZÜ EARTHQUAKE

EMSC manual location

M:7.5 2023/02/06 - 10:24:49 UTC

Lat: 38.11 Lon: 37.24 Depth: 10 km

Population: 57 Millions inhabitants in a radius of 400 km from the earthquake epicenter



Depth

- ★ 0 - 40 km
- ★ 40 - 80 km
- ★ 80 - 150 km
- ★ 150 - 300 km
- ★ > 300 km

20 km

Political boundaries

Tectonic plates boundaries (Bird, P. [2003])

Last updated: 2023-02-06 at 11:08 UTC

(from CSEM-EMSC)

MAIN CHARACTERISTICS OF THE EARTHQUAKES

The Pazarcık earthquake occurred at 4:17 (TST) on February 6, 2023 and the Ekinözü earthquake occurred at 13:24 on the same day after about 9 hours. The earthquake involve rupturing on the segments of East Anadolu Fault (EAF) and Dead-Sea Fault. The initial total length of Pazarcık earthquake was about 210-230 km and reach to a total length of 400-450 km. Ekinözü earthquake E-W trending Çardak and Sürgü faults with a total length of 120-130 km. As of 15 February 2023,

Number of casualties is 35.418.

Number of injured people is more than 105.505.

Number of after shocks is more than 1.900.

10 provinces with a total population of 15 million people were affected.

Affected provinces



MAIN CHARACTERISTICS OF THE EARTHQUAKES


PAZARCIK EARTHQUAKE

The earthquake occurred at 4:17:35 (TST) (1:17:35 GMT) on NE-SW trending fault with sinistral slip. This fault might be a combined slip of East Anatolian Fault and Dead-Sea Fault. Moment magnitude of this earthquake has been estimated by different institutes and they range between 7.7 and 8.0.

| Institute | Mw | LAT | LON | Depth (km) | Fault Plane | | | Auxiliary Plane | | |
|-----------|-----|------|------|------------|-------------|-----|------|-----------------|-----|------|
| | | | | | Strike | Dip | Rake | Strike | Dip | Rake |
| QCMT | 7.8 | 37.6 | 37.5 | 15 | 54 | 70 | 11 | 320 | 80 | 160 |
| USGS | 7.9 | 37.4 | 37.8 | 33 | 234 | 79 | 14 | 142 | 76 | 169 |
| KOERI | 7.7 | 37.1 | 37.1 | 10 | 222 | 64 | -27 | 324 | 65 | -152 |
| ERD | 7.8 | 37.2 | 37.1 | 18 | 233 | 74 | 18 | 140 | 77 | 168 |
| IPGP | 8.0 | 37.2 | 37.0 | 13 | 230 | 81 | -18 | 323 | 72 | -171 |

Moment Tensor map of earthquake:

Mag: 7.8 2023-02-06 01:17:36 UTC
Lat: 37.17 Lon: 37.08 Depth: 20.0 km



Among all focal plane solutions, focal plane by KOERI is close to the actual situations.

(from CSEM-EMSC)


EKİNÖZÜ EARTHQUAKE

The earthquake occurred at 13:24:49 (TST) (10:24:49 GMT) on almost E-W trending fault with sinistral slip. This fault might be a combined slip of Çardak and Sürgü Faults. Moment magnitude of this earthquake has been estimated by different institutes and they range between 7.6 and 7.7.

| Institute | Mw | LAT | LON | Depth (km) | Fault Plane | | | Auxiliary Plane | | |
|-----------|-----|------|------|------------|-------------|-----|------|-----------------|-----|------|
| | | | | | Strike | Dip | Rake | Strike | Dip | Rake |
| QCMT | 7.7 | 38.1 | 37.2 | 12 | 261 | 42 | -8 | 358 | 84 | -132 |
| USGS | 7.6 | 38.0 | 37.2 | 19 | 276 | 82 | -6 | 6 | 85 | -172 |
| KOERI | 7.6 | 38.0 | 37.3 | 10 | 273 | 67 | -9 | 6 | 81 | -157 |
| ERD | 7.6 | 38.0 | 37.2 | 16 | 174 | 90 | 13 | 358 | 73 | 174 |
| IPGP | 7.7 | 38.0 | 37.2 | 13 | 270 | 60 | -9 | 5 | 82 | -150 |

Moment Tensor map of earthquake:

Mag: 7.5 2023-02-06 10:24:49 UTC
Lat: 38.11 Lon: 37.24 Depth: 10.0 km




Earthquake occurred in north dipping fault and large ground subsidence occurred on the northern part.

(from CSEM-EMSC)


Estimation of the Earthquake Parameters

Estimation of the earthquake parameters from fault length (based on relations of Aydan, 2012, 2023). AMAX and VMAX are computed for a hypocenter distance of 14 km and surface shear wave velocity of 300 m/s.


| Length | Mw | AMAX (gals) | VMAX (kines) | DMAX (cm) | Tr (s) |
|--------|-----|----------------|-----------------|--------------|-----------|
| 147 | 7.6 | 1020,3 | 72.9 | 506 | 35.6 |
| 195 | 7.8 | 1217.6 | 87.0 | 721 | 45.8 |
| 222 | 7.9 | 1320.7 | 94.3 | 848.4 | 51.4 |
| 255 | 8.0 | 1440.6 | 102.3 | 1009.5 | 58.2 |



TECTONICS



(From Ulusay and Aydan (2005) based on the original drawing by Gülen et al.(2002))




(From Palutoğlu and Şaşmaz, 2017)


GEOLOGY

Regional Geology of the Affected Region

TÜRKİYE JEOLJİ HARİTASI / GEOLOGICAL MAP OF TURKEY
HATAY




(From MTA)




(Yılmaz et al., 1993)

Geology and Faults of Hatay (Antakya)




(From Korkmaz, 2006)

Geology and Faults of Osmaniye




(From MTA)

(From Emre et al., 2013)




Geology and Faults of Kahramanmaraş


(From Sandal and Karademir, 2013)



(From Emre et al., 2013)




Geology and Faults of Malatya




(From Önal, 2007)


PRE- AND POST-SEISMICITY




(From Palutoğlu and Şaşmaz, 2015)



(DbA, base map by Aydan, unpublished)



The Pazarcık earthquake involved EAFZ (2 segments) and DSF-Death Sea Fault (1 segment). The total length of the surface rupture could be in the order of 210-230 kms.




(DbA, base map by Aydan, unpublished)


FOCAL MECHANISM AND ASSOCIATED STRESS FIELD

THE PAZARCIK EARTHQUAKE

FOCAL MECHANISM




ASSOCIATED STRESS FIELD




Inferred crustal stresses of the epicentral area for focal plane solution by KOERI using Aydan's Method (Aydan 2000a, 2016, 2020). KOERI focal mechanism involves normal component as observed in-situ (DbA).

THE EKİNÖZÜ EARTHQUAKE

FOCAL MECHANISM




ASSOCIATED STRESS FIELD




Inferred crustal stresses of the epicentral area for focal plane solution by KOERI using Aydan's Method (Aydan 2000a, 2016, 2020). Pazarcık earthquake greatly altered the stress state. On the northern side, some downward motions are reported (DbA)

CRUSTAL STRESSES





Annual principal stress rates of Türkiye (Aydan, 2000b)
inferred from GPS measurements



Maximum horizontal stress directions (Aydan, 2020)

SURFACE DEFORMATION FROM GPS & DINSAR



GPS



Displacement reflects the expected faulting movements

(From Nevada Geodetic Laboratory

/NVGeodeticLab/status/1625241970460491777/photo/1)



(From Dr. C. Milliner, 2023, JPL, USA)


The Pazarcık earthquake caused about 5-6 m sinistral slip and the distribution has a parabolic shape. While the Ekinözü earthquake has the same sense of relative slip, the shape is triangular

Surface Ruptures

Tevekkeli




Tevekkeli




(Photos: Internet)

(DbA)



Gölbaşı



Şekeroba

Kırıkhan




Hassa



















Relative slip is generally more than 300 cm in many rupture observations and the southern rupture has also normal component. This may also explain why some part of İskenderun city subsided and immersed by sea-water. Şekeroba – Kırıkhan segment is on Dead Sea fault.

STRONG MOTION RECORDS















Turkish Strong Motion Network (TADAS) has recorded the motions induced by Pazarcık and Ekinözü earthquakes. In this report, the strong motion caused by the Pazarcık earthquakes are reported and discussed. The stations along the fault rupture and Arabian Plate recorded much higher ground motions and duration of shaking was more than 70 seconds and it was about more than 220 seconds at Şanlı Urfa. Next figures show strong motion records for selected 16 cities. Response spectra of 12 cities are plotted. The response spectra generally exceed the seismic design spectra of Türkiye. Furthermore, maximum ground accelerations in affected cities exceed the maximum ground acceleration assumed in the seismic code particularly at locations near earthquake rupture. This simply implies that the design code should be revised.







Response Spectra of the selected stations







Response spectra of selected acceleration records near the fault




TSC: Turkish Seismic Code

Response spectra of acceleration records at the selected heavily damaged cities




TSC: Turkish Seismic Code


Attenuation of Strong Motions with Distance



Original drawings from Aydan 2012, DbA)




Original drawings from Aydan 2012, DbA)



(DbA)

The vertical component of strong motions near the fault rupture is quite high and it decays with distance



(Aydan 2023)

Most of RC buildings has 5 to 14 stories. The estimated natural frequency for the first mode ranges between 0.3 to 0.9 seconds, this might have an influence on their collapses. If the design and construction were properly done according to the Turkish Seismic Code, this scale damage would not occur

TRANSPORTATION FACILITIES

Roadways



The map of Damaged Roadways from KGM (General Directorate of Highways of Turkey) (yellow lines indicates roadways closed to traffic due to damage)

Damage occurred due to

- 1) Separation or collision of bridge deck with abutments
- 2) Faulting induced deformations
- 3) Retaining wall failures
- 4) Deformation of pavement (separation or buckling=)
- 5) Fall of bridge decks
- 6) Tunnel damage
- 7) Embankment failures

The above damages occurred along Tarsus-Adana-Gaziantep Highway, Malatya Adıyaman Highway, Kahramanmaraş-Malatya highways.

Roadways



Separation or collision of bridge deck with abutments



Bridge deck fall


(Photos: Internet)

Hatay Airport road



(Photos: Internet)

Damage of Tarsus Adana Gaziantep (TAG) near Islahiye by the fault rupture



(Photos: Internet)

Topped stationary vehicles



Adiyaman-Malatya highway *(Photos: Internet)*



Tunnel Damages

Rockfalls at the portal and spalling of concrete lining of the Erkenek Tunnel occurred as reported by KGM. One of Erkenek Tunnel tubes is closed to traffic while the other is utilised for traffic despite some spalling location of the lining were reported at some locations. The tunnel was almost on the activated Erkenek fault.



Location of Erkenek tunnel



Traces and Rockfalls above the portals of Erkenek tunnel

(Photo: Internet)

Spalling of concrete linings in Erkenek Tunnel



(Photos: Internet)

Railways



Locations of the damaged railway lines (from TCDD)

Damage was mainly caused by deformation of rails wherever earthquake faults crossed. In addition, trains and wagons were derailed or toppled. Rockfalls and slope failures also caused obstructions.



(Photos: Internet)

Derailed and toppled wagons at Gölbaşı Train Station



(Photos: Internet)

Deformed rails in Gölbaşı




(Photos: Internet)


Islahiye-Fevzipaşa Train Station



(Photos: Internet)



Airports



Kaynak: dhmi.gov.tr 2019 © Haritanın tüm hakları saklıdır

cografyaharita.com R.SAYGILI 2020

Airports of Türkiye. The circle indicates the airports in the epicentral area

(Photos: Internet)



Gaziantep Airport at the time of Pazarcık earthquake occurred. Note the small pieces of debris falling from the suspended ceilings. Similar situation occurred at Malatya Airport.

Hatay Airport

(Photos: Internet)



Ground settled around the terminal building at Hatay Airport



Runway buckled at Hatay Airport



Under reparation

Runway was repaired on February 11, 2023



Test flight on February 11, 2023





First flight was done on February 12, 2023

Ports



Iskenderun Port

(Photos: Internet)



Fire at Iskenderun Port

(Photos: Internet)




GEOTECHNICAL DAMAGES

Rockfalls

(Photos: Internet)



Slope Failures (Landslides)




(Photos: Internet)


Liquefaction and Lateral Spreading



Antakya-Reyhanlı Highway



Near Çöçelli village



Gölbaşı

(Photos: Internet)

Sinkholes




Gaziantep Yavuzlar
District

(Photos: Internet)



DAMS

Kartalkaya Dam



Sultansuyu Dam



Sürgü Dam



Sürgü Dam



(Photos: Internet)

Atatürk Dam

The third largest rockfill dam in the world. 169 m high and epicentral distance is about 90 km. No damage was reported.



Areal view after the earthquakes



Aerial inspection by the minister

(Photos: Internet)

Landslide Dams





Islahiye



Tepehan

(Photos: Internet)

LIFELINES



(Photos: Internet)

DAMAGED AND COLLAPSED STRUCTURES

Reinforced Concrete (RC) Building Damages

The totally collapsed or heavily damaged school, residential and office buildings had mainly 3-14 stories. These structures are designed as moment-resistant frame structures with in-fill walls made of hollow bricks. The failure of RC structures was due to soft-story (weak-floor) situation as it is a common problem resulting in high casualties in earthquakes since 1960. The ground floors of collapsed buildings were mostly used as either shops, depots or garages. As a result, this type of usage constitutes a weak(soft)-floor situation. Furthermore, many buildings had heavy balconies of cantilever type.

The causes of the damage were almost the same as those seen in the previous earthquakes of Turkey. The causes listed below are taken from the reports by the first author on March 13, 1992 Erzincan Earthquake with few amendments and additions from the reports of the Turkish earthquakes occurred after 1992 (Aydan et al., 1998; Aydan et al., 2000a, b; Ulusay et al., 2002; Aydan et al., 2003; Aydan et al., 2012):

Poor workmanship: There are two kinds of poor workmanship. One of them is that the connections of columns and beams were very weak since the connections of steel bars were not properly done. The second one is that the granulometry of the sand and gravel of concrete was very poor and the range was wide. In addition, big chunks of gravel blocked the concrete during casting at locations where steel connections were dense and this resulted in very porous and weak connections. During shaking, it seems that concrete at the connections first failed and this subsequently caused the buckling of steel bars at such locations and rupturing in-fill hollow brick walls in a brittle sense. As a result, the collapse of buildings ended up in a pancake mode.

Construction negligence and lack of moral: One of the most striking construction negligence was the confinement of concrete at the beam-column connections in spite of the Turkish design code for seismic regions. As stir-ups were very few at such locations, the failure of concrete was very brittle and it could not absorb the work done by the earthquake forces.

Resonance: Natural periods of collapsed buildings mostly coincided with those of the input waves and this resulted in the resonance-like shaking of structures and their subsequent collapses.

Soft Story: Many buildings had shops at their ground floor. As there are generally no shear-walls to take up the load during earthquakes, the total load is transferred onto the columns. The super structure acts as a top-heavy structure on the columns and in-fill walls, which are in poor contact with columns and beams, has no effect against the earthquake loading and they fail subsequently.

Pounding of adjacent structures: Buildings at the corners of streets were mostly collapsed as a result of pounding with the adjacent building.

Adiyaman



Gaziantep



Hatay



Hatay



Buildings with problematic issues mentioned above


(Photos: Internet)

Views of Building Damages

(Photos: Internet)



Kahramanmaraş



Antakya (Hatay)



Diyarbakır



Gaziantep

Gaziantep



(Photos: Internet)



Kahramanmaraş



Diyarbakır



Antakya



Before



After

Adıyaman

(Photos: Internet)



Malatya



Adiyaman



Antakya



Antakya



Antakya

SEARCH AND RESCUE



Many countries continue to direct their search and rescue teams to Turkey.



| | | |
|--|------------------------|-----|
| | Azerbaijan | 725 |
| | USA | 159 |
| | Germany | 50 |
| | Albania | 63 |
| | Austria | 105 |
| | BAE | |
| | Belarus | 32 |
| | Bosnia and Herzegovina | 104 |
| | Bulgaria | 59 |
| | Algeria | 89 |
| | Czech Republic | 68 |
| | China | 82 |
| | El Salvador | 100 |
| | Armenia | 57 |
| | Estonia | |
| | Palestine | 35 |
| | France | 204 |
| | South Africa | 69 |
| | South Korea | 118 |
| | Georgia | 100 |
| | Croatia | 40 |
| | India | 201 |
| | Holland | |
| | Iraq | 150 |
| | England | 77 |
| | Iran | 80 |

The total number of personnel sent to the earthquake zone

| | | |
|--|-------------|-----|
| | Spain | 90 |
| | Israel | 450 |
| | Sweden | |
| | Switzerland | 80 |
| | Italy | |
| | Japan | 73 |
| | Montenegro | 15 |
| | Train | |
| | Kazakhstan | 60 |
| | Kyrgyzstan | 63 |
| | TRNC | 200 |
| | Kosovo | 30 |
| | Kuwait | 46 |
| | Libya | 55 |
| | Lebanon | 72 |
| | Hungary | 156 |
| | Malta | 32 |
| | Mexican | 145 |

TURKEY

| | | |
|--|--------------|-----|
| | Mongolia | 35 |
| | Moldova | 55 |
| | Uzbekistan | 100 |
| | Pakistan | 52 |
| | Poland | 76 |
| | Portugal | |
| | Romania | |
| | Russia | 150 |
| | Serbia | 27 |
| | Slovakia | |
| | Tajikistan | 51 |
| | Taiwan | 44 |
| | Tunisia | 41 |
| | Turkmenistan | 10 |
| | Ukraine | 87 |
| | Venezuela | 50 |
| | Greece | 41 |

09.02.2023



(Photos: Internet)

(Photos: Internet)



Turkish Ambassador thanking to Japanese Rescue Team



Korean Rescue Team



Turkish governmental airplanes played great role in transferring injured people to the hospitals in non-affected cities



Turkish Army, Miners and AFAD played great role in rescue operations

EVACUATION AND IMMEDIATE HOUSING



TCG for evacuation peoples



Tent village at Gaziantep



Kızılay (Red Crescent) offers hot meal.



Traditional Turkish Tents 'Yurts' by Kirgizistan



Field hospital

(Photos: Internet)

UNUSUAL OBSERVATIONS

Earthquake lights occurred during the fault rupture process. The authors also observed the same phenomenon during 1999 Kocaeli Earthquake (Aydan et al., 2000a) and in laboratory experiment on rocks.



Barking dogs just before the earthquake



Blue lightning in Hatay



Blue lightning in Adiyaman

(Photos: Internet)

Earthquake lights in Kahramanmaraş



(Photos: Internet)



Before the earthquake transparent
Balıklıgöl, Şanlı Urfa



After the earthquake muddy Balıklıgöl,
Şanlı Urfa



Before the earthquake transparent Gökpınar Lake, Gürün, Sivas (124 km
from M7.8 epicenter)



After the earthquake muddy Gökpınar Lake, Gürün, Sivas

References

AFAD- TADAS Afet ve Acil Durum Yönetimi Başkanlığı, Deprem Dairesi Başkanlığı, Türkiye İvme Veri Tabanı ve Analiz Sistemi, <https://tadas.afad.gov.tr/>

Aydan, Ö., 1997. The seismic characteristics and the occurrence pattern of Turkish Earthquakes. Turkish Earthquake Foundation, Publication No. TDV/TR 97-007, 40 p.

Aydan, Ö., 2000a. A new stress inference method for the stress state of earth's crust and its application. *Yerbilimleri*, 22, 223-236.

Aydan, Ö., 2000b. Assessment of annual strain rate distributions of Turkey from GPS measurements. *Yerbilimleri*, 22, 21-31 (Makalenin başlığı hatalı yazılmış, düzelttim)

Aydan, Ö., 2012. Ground motions and deformations associated with earthquake faulting and their effects on the safety of engineering structures. *Encyclopedia of Sustainability Science and Technology*, Springer, R. Meyers (Ed.), pp. 3233-3253.

Aydan, Ö., 2016. An integrated approach for the evaluation of measurements and inferences of in-situ stresses. RS2016 Symposium, 7th Int. Symp. on In-situ Rock Stress, Tampere, pp. 38-57.

Aydan, Ö., 2020. *Rock Mechanics and Rock Engineering: Fundamentals*, Vol.1, CRC Press, Taylor and Francis Group, 412 p.

Aydan, Ö., 2023. *Earthquake Science and Engineering*, CRC Press, Taylor and Francis Group, 499 p.

Aydan, Ö., Ulusay, R., Kumsar, H., Sönmez, H., Tuncay, E., 1998. A site investigation of Adana-Ceyhan Earthquake of June 27, 1998. Turkish Earthquake Foundation, Publication No. TDV/DR 006-30 November 1998, 131 p (*in English*)

Aydan, Ö., Ulusay, R., Hasgür, Z., Taşkın, B., 2000a. A site Investigation of Kocaeli Earthquake of August 17, 1999. Turkish Earthquake Foundation, Publication No. TDV/DR 08-49, 180 p (*in English*).

Aydan, Ö., Ulusay, R., Kumsar, H., Tuncay, E., 2000b. Site Investigation and Engineering Evaluation of the Düzce-Bolu Earthquake of November 12, 1999. Turkish Earthquake Foundation, TDV/DR 09-51, 300 p (*in English and Turkish*).

Aydan, Ö., Ulusay, R., Miyajima, M., 2003. The Bingöl earthquake of May 1, 2003. Report of the Japan Society of Civil Engineers. Japan Society of Civil Engineers, Tokyo, Japan, 103 p. (<http://www.jsce.org.jp/report/19/frame.htm>) (*in English*)

Aydan, Ö., Ulusay, R., Kumsar, H., 2012. Site investigation and engineering evaluation of the Van earthquakes of October 23 and November 9, 2011. Turkish Earthquake Foundation, Report No. TDV/DR 015-92, March 2012, İstanbul, 190 p (*English and Turkish*).

Boğaziçi Üniversitesi Kandilli Rasathanesi ve Deprem Araştırma Enstitüsü (KRDAE), Bölgesel Deprem-Tsunami İzleme Ve Değerlendirme Merkezi (BDTİM)
<http://www.koeri.boun.edu.tr/sismo/2/tr/>.

Emre, Ö., Duman, T.Y., Özalp, S., Elmacı, H., Olgun, Ş., Şaroğlu, F., 2013, Açıklamalı Türkiye Diri Fay Haritası, Ölçek 1:1.250.000. Maden Tetkik ve Arama Genel Müdürlüğü, Özel Yayın Serisi-30, Ankara. ISBN: 978-605-5310-56-1.

Gulen, L., Pınar, A., Kalafat, D., Ozel, N., Horasan, G., Yilmazer, M., Isıkara, A.M., 2002. Surface fault breaks, aftershock distribution and rupture process of the 17 August 1999 Izmit, Turkey earthquake. Bull. Seismological. Soc. Am. 92 (1), 230–244.

Korkmaz, H. 2006. ***The Relationship Between Ground Conditions and Earthquake Effect In Antakya***. Coğrafi Bilimler Dergisi, 2006, 4 (2), 49-66 (in Turkish).

MTA, 2023. 06 Şubat 2023 Pazarcık (Kahramanmaraş) (Mw 7,7) ve Elbistan (Kahramanmaraş) (Mw 7,6) depremleri bilgi notu. MTA Jeoloji Etütleri Daiesi Başkanlığı, Ankara 10 s.

Önal, M, 2007. Malatya ve dolaylaronın depremeselliği. Unpublished presentation.

Palutoğlu, M. and Şaşmaz, A. 2017. 20 November 1795 Kahramanmaraş earthquake, Southern Turkey. MTA Dergisi (Bulletin) 155: 191-206 (in Turkish).

Sandal, E.K., and Kandemir, N., 2013. The Relationship between Ground Conditions and Earthquake Based on Seismicity in Kahramanmaraş. 3rd International Geography Symposium - GEOMED 2013, 474-488.

USGS, United States Geological Survey, <https://earthquake.usgs.gov/earthquakes>

Ulusay, R., Aydan, Ö., 2005. Characteristics and geo-engineering aspects of the 2003 Bingöl (Turkey) earthquake. Journal of Geodynamics, 40, 334-346.

Ulusay, R., Aydan, Ö., Erken, A., Kumsar, H., Tuncay, E., Kaya, Z., 2002. Site Investigation and Engineering Evaluation of the Çay-Eber Earthquake of february 3 2022,. Turkish Earthquake Foundation Research Project No. 02-AP-119, Publication No. . TDV/DR 012-79, 213 s (*in Turkish*).

Ulusay, R., Tuncay, E., Sönmez, H., Gökçeoğlu, C., 2004. An attenuation relationship based on Turkish strong motion data and iso-acceleration map of Turkey. Engineering Geology, 74, 265-291.

Wells, D.L., Coppersmith, K.J., 1994. New Empirical Relationships among Magnitude, Rupture Length, Rupture Width, Rupture Area and Surface Displacement. Bulletin of Seismological Society of America, 84 (4), 974-1002.

Yılmaz, Y., Yiğitbaş, E., and Genç, C., 1993. Ophiolitic and metamorphic assemblages of southeast Anatolia and their significance in the geological evolution of the orogenic belt. Tectonics, 12, p. 1280–1297.